

GENERAL INFORMATION

| | |
|-----------------|------------------------|
| Report Name | Mercedes Sprinter 2019 |
| Serial number | 10373 PROFESSIONAL |
| Unit of measure | µm |


VEHICLE DATA

| | |
|-----------------------|-------------------|
| Type | VAN |
| Make | Mercedes Benz |
| Model | Sprinter |
| Engine capacity [ccm] | 2143 |
| Power [kW] | - |
| VIN | WDB9106231P179354 |
| Fuel Type | Diesel |
| Year of production | 2019 |

MEASUREMENTS

"-" means measurement skip, "∞" means measurement out of range

PAS: general interpretation, body



LEFT FRONT FENDER/ BUMPER

| Coating | Fe |
|---------|-----|
| Minimum | 82 |
| Maximum | 123 |
| Medium | 103 |
| 1. | 105 |
| 2. | 82 |
| 3. | 123 |

LEFT FRONT DOOR

| Coating | Fe |
|---------|-----|
| Minimum | 79 |
| Maximum | 118 |
| Medium | 99 |
| 1. | 79 |
| 2. | 100 |
| 3. | 118 |
| 4. | 90 |
| 5. | 106 |

LEFT PILLAR


| Coating | Fe |
|---------|----|
| Minimum | 55 |
| Maximum | 96 |
| Medium | 81 |
| 1. | 55 |
| 2. | 92 |
| 3. | 96 |

LEFT REAR DOOR

| Coating | Fe |
|---------|-----|
| Minimum | 77 |
| Maximum | 124 |
| Medium | 96 |
| 1. | 103 |
| 2. | 84 |
| 3. | 124 |
| 4. | 83 |
| 5. | 90 |
| 6. | 77 |
| 7. | 112 |

LEFT REAR FENDER/ BUMPER

| Coating | Fe |
|---------|-----|
| Minimum | 76 |
| Maximum | 706 |
| Medium | 174 |
| 1. | 88 |
| 2. | 84 |
| 3. | 76 |
| 4. | 113 |
| 5. | 100 |
| 6. | 122 |
| 7. | 121 |
| 8. | 153 |
| 9. | 706 |



RIGHT REAR FENDER/BUMPER

| Coating | Fe |
|---------|-----|
| Minimum | 71 |
| Maximum | 339 |
| Medium | 137 |
| 1. | 93 |
| 2. | 76 |
| 3. | 71 |
| 4. | 129 |
| 5. | 103 |
| 6. | 188 |
| 7. | 129 |
| 8. | 106 |
| 9. | 339 |

RIGHT REAR DOOR

| Coating | Fe |
|---------|-----|
| Minimum | 83 |
| Maximum | 136 |
| Medium | 108 |
| 1. | 110 |
| 2. | 103 |
| 3. | 107 |
| 4. | 83 |
| 5. | 136 |
| 6. | 98 |
| 7. | 121 |

RIGHT PILLAR


| Coating | Fe |
|---------|-----|
| Minimum | 99 |
| Maximum | 143 |
| Medium | 118 |
| 1. | 99 |
| 2. | 112 |
| 3. | 143 |

RIGHT FRONT DOOR

| Coating | Fe |
|---------|-----|
| Minimum | 77 |
| Maximum | 112 |
| Medium | 97 |
| 1. | 90 |
| 2. | 112 |
| 3. | 108 |
| 4. | 77 |
| 5. | 96 |


RIGHT FRONT FENDER/BUMPER

| Coating | Fe |
|---------|----|
| Minimum | 40 |
| Maximum | 60 |
| Medium | 51 |
| 1. | 54 |
| 2. | 40 |
| 3. | 60 |



TRUNK/BOOT

| | |
|---------|-----|
| Coating | Fe |
| Minimum | 71 |
| Maximum | 258 |
| Medium | 121 |
| 1. | 121 |
| 2. | 73 |
| 3. | 71 |
| 4. | 122 |
| 5. | 258 |
| 6. | 79 |



HOOD/BONNET

| | |
|---------|-----|
| Coating | Fe |
| Minimum | 78 |
| Maximum | 130 |
| Medium | 103 |
| 1. | 109 |
| 2. | 78 |
| 3. | 130 |
| 4. | 89 |
| 5. | 110 |

ROOF

| | |
|---------|-----|
| Coating | Fe |
| Minimum | 112 |
| Maximum | 160 |
| Medium | 124 |
| 1. | 117 |
| 2. | 160 |
| 3. | 115 |
| 4. | 112 |
| 5. | 117 |