

REPORT

GENERAL INFORMATION

Report Name	VW Caddy TGI
Read out date	2025-07-31 11:03:13
Date of editing	2025-07-31 11:03:13
Serial number	10373 PROFESSIONAL
Unit of measure	µm

VEHICLE DATA

Type	VAN
Make	VW
Model	Caddy
Engine capacity [ccm]	-
Power [kW]	-
VIN	-
Fuel Type	-
Year of production	-


COMMENT

-

MEASUREMENTS

"-" means measurement skip, "∞" means measurement out of range

PAS: general interpretation, body



LEFT FRONT FENDER/ BUMPER

Coating	Fe+Zn
Minimum	72
Maximum	88
Medium	81
1.	72
2.	88
3.	84

LEFT FRONT DOOR

Coating	Fe
Minimum	81
Maximum	102
Medium	90
1.	102
2.	91
3.	86
4.	90
5.	81

LEFT PILLAR


Coating	Fe+Zn
Minimum	91
Maximum	139
Medium	108
1.	91
2.	139
3.	94

LEFT REAR DOOR

Coating	Fe+Zn
Minimum	76
Maximum	98
Medium	85
1.	76
2.	98
3.	79
4.	96
5.	82
6.	78
7.	89

LEFT REAR FENDER/ BUMPER

Coating	Fe
Minimum	73
Maximum	154
Medium	96
1.	73
2.	101
3.	83
4.	78
5.	102
6.	95
7.	154
8.	99
9.	83



RIGHT REAR FENDER/ BUMPER

Coating	Fe+Zn
Minimum	84
Maximum	146
Medium	97
1. 93	
2. 97	
3. 89	
4. 85	
5. 84	
6. 85	
7. 146	
8. 104	
9. 88	

RIGHT REAR DOOR

Coating	Fe+Zn
Minimum	91
Maximum	118
Medium	100
1. 109	
2. 99	
3. 93	
4. 118	
5. 99	
6. 91	
7. 94	

RIGHT PILLAR


Coating	Fe+Zn
Minimum	81
Maximum	122
Medium	97
1. 81	
2. 122	
3. 87	

RIGHT FRONT DOOR

Coating	Fe+Zn
Minimum	88
Maximum	122
Medium	101
1. 88	
2. 96	
3. 122	
4. 106	
5. 94	


RIGHT FRONT FENDER/BUMPER

Coating	Fe
Minimum	96
Maximum	115
Medium	107
1. 111	
2. 96	
3. 115	



TRUNK/BOOT

Coating	Fe+Zn
Minimum	72
Maximum	113
Medium	86
1. 100	6. 79
2. 113	
3. 73	
4. 72	
5. 77	



HOOD/BONNET

Coating	Fe+Zn
Minimum	72
Maximum	92
Medium	80
1. 72	
2. 92	
3. 72	
4. 88	
5. 77	

ROOF

Coating	Fe+Zn
Minimum	86
Maximum	129
Medium	104
1. 92	
2. 129	
3. 106	
4. 107	
5. 86	