

REPORT

GENERAL INFORMATION

Report Name

Toyota land Cruiser

Read out date

2025-03-17 11:45:43

Date of editing

2025-03-17 11:57:59

Serial number

10373 PROFESSIONAL

Unit of measure

µm


VEHICLE DATA

Type	SUV
Make	Toyota
Model	Land Cruiser GR
Engine capacity [ccm]	3346
Power [kW]	220
VIN	JTMAAABJ904041510
Fuel Type	Diesel
Year of production	-


MEASUREMENTS

"-" means measurement skip, "∞" means measurement out of range


PAS: general interpretation, body




LEFT SIDE											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
left front fender/ bumper	Al	96	101	98	96	101	97	97	-	-	-
left front door	Al	90	127	109	90	112	113	127	101	-	-
left rear door	Al	102	121	114	118	121	119	109	102	-	-
left pillar	Fe	118	150	134	150	143	127	118	-	-	-
left rear fender/ bumper	Fe	121	162	141	162	150	121	128	144	-	-



RIGHT SIDE											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
right front fender/ bumper	Al	91	117	107	91	111	110	117	-	-	-
right front door	Al	100	137	116	100	117	113	114	137	-	-
right rear door	Al	108	115	112	115	108	111	114	110	-	-
right pillar	Fe	116	128	120	117	116	119	128	-	-	-
right rear fender/ bumper	Fe+Zn	116	165	142	141	142	116	144	165	-	-




TOP											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
hood/bonnet	Al	91	115	99	92	91	115	103	93	-	-
roof	Al	121	153	131	121	123	125	134	153	-	-



BACK											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
trunk/boot	Al	90	107	100	107	104	90	-	-	-	-

Legend

- Disabled
- Paint layer is too thin
- Paint layer is original
- Second layer of paint
- A thin layer of putty
- A thick layer of putty



SYMMETRIC MEASUREMENTS

EXTERNAL MEASUREMENTS														
left front fender/ bumper	1. 96	2. 101	3. 97	4. 97	-	-	-	-	-	-	-	-	-	-
right front fender/ bumper	4. 117	3. 110	2. 111	1. 91	-	-	-	-	-	-	-	-	-	-
DIFFERENCE	21	9	14	6										
left front door	1. 90	2. 112	3. 113	4. 127	5. 101	-	-	-	-	-	-	-	-	-
right front door	5. 137	4. 114	3. 113	2. 117	1. 100	-	-	-	-	-	-	-	-	-
DIFFERENCE	47	2	0	10	1									
left rear door	1. 118	2. 121	3. 119	4. 109	5. 102	-	-	-	-	-	-	-	-	-
right rear door	5. 110	4. 114	3. 111	2. 108	1. 115	-	-	-	-	-	-	-	-	-
DIFFERENCE	8	7	8	1	13									
left pillar	1. 150	2. 143	3. 127	4. 118	-	-	-	-	-	-	-	-	-	-
right pillar	4. 128	3. 119	2. 116	1. 117	-	-	-	-	-	-	-	-	-	-
DIFFERENCE	22	24	11	1										
left rear fender/ bumper	1. 162	2. 150	3. 121	4. 128	5. 144	-	-	-	-	-	-	-	-	-
right rear fender/ bumper	5. 165	4. 144	3. 116	2. 142	1. 141	-	-	-	-	-	-	-	-	-
DIFFERENCE	3	6	5	14	3									